

How to make an external corner:

1. Lay all **complete ramps** (fig.1) **A, B, C, D** until only the corner remains to be completed.

2. Using a **spare ramp (E)**...



Cut triangle **e2** off **E** following the marking on the underside of the ramp. Do the same for triangle **e1**.

3. Discard the remainder of **ramp E**.




Fig. 2

4. Lay **e2** next to **ramp A** and **e1** next to **ramp D** (fig 2).

This will complete your corner.

fig. 1

